



SERVICE BULLETIN



WORLDLAWN POWER EQUIPMENT, INC.
2415 Ashland Ave
Beatrice, NE 68310
(402) 228-4255

Bulletin Number: SB1406

Date: 8/15/14

Product Affected: WYK52FX730V5 & WYK60FX801V5 King Cobra mowers with serial numbers 201407U01147 and below

Situation: We had several field complaints on units with low hours showing wear between the console T-slot and the motion control arms. Although the wear would not cause any component failure, the motion control lever should not be rubbing on the console.

Solution: The motion control pivot design was changed to add a stop tab. This will prevent the motion control arm from contacting the console. Since there may be wear on both the console and control arm, both items are included in the kit.

Parts Required: 542122 motion control kit
One kit per unit.

Warranty: Warranty will cover the cost of the kit and labor to install them for any unsold units or units reporting this condition in the warranty period.