



# SERVICE BULLETIN



**WORLDLAWN POWER EQUIPMENT, INC.**  
2415 Ashland Ave  
Beatrice, NE 68310  
(402) 228-4255

**Bulletin Number: SB1408**  
**Date: 8/15/14**

**Product Affected: All Worldlawn WY32 Mowers**

**Situation:** We had several customer requests to improve the wheel drive belt pulling performance. This is not to say that this belt will resolve all issues. Care needs to be taken to troubleshoot any drive performance issues. Following is a list of potential trouble areas.

- Transmission belt is properly adjusted.
- The idler pulley pivots aligned and working freely.
- The drive lever linkage is properly adjusted so it does not bottom out in the drive lever slot.
- The brake mechanism is not hanging up and putting a drive on the control mechanism.

**Solution:** Working with our customers and suppliers we found a belt that improved pulling performance.

**Parts Required:** 323042 WY-32 wheel drive belt, order and stock the belt as needed.

**Warranty:** The replacement to the optional wheel drive belt is not a warrantable update. Should any warrantable failures occur it is acceptable to use the optional belt instead of the standard belt for replacement.