



SERVICE BULLETIN



WORLDLAWN POWER EQUIPMENT, INC.
2415 Ashland Ave
Beatrice, NE 68310
(402) 228-4255

Bulletin Number: SB2001
Date: 3/6/2020

Product Affected: Worldlawn Viper
WYRZ42S18KW WYRZ46XS22KW WYRZ50XL24KW WYRZ60XL24KW

Serial Range 201712P5001724 - 201812P5002860

Discrepancy: Fuel filter is positioned close to the under side of the seat assembly.

Solution: Relocate fuel filter. See attached instruction sheets

Parts Required: None

Warranty: Warranty will reimburse \$20.00 per unit for relocating the fuel filter. Multiple units can be filed on one claim. List additional serial numbers in the notes section of the claim form.